



**Welcome to the BMW TIS website.**



SI B01 01 15  
Warranties

---

**SUBJECT**

**N63 Engine Fuel Injectors – Limited  
Warranty Extension to 10  
Years/120,000 Miles**

**MODEL**

E70 (X5 xDrive 50i)

Model Year 2011 produced 11/18/2009 to  
3/28/2011

E71 (X6 xDrive 50i)

Model Years 2009, 2010 and 2011  
produced 9/22/2008 to 3/26/2011

F01 (750i Sedan)

Model Year 2009, 2010 and 2011  
produced from 5/15/2008 to 2/3/2010

F01 (750i xDrive Sedan)

Model Year 2010 produced from  
5/25/2009 to 2/3/2010

F02 (750i Sedan LWB)

Model Year 2009, 2010 and 2011  
produced from 3/12/2008 to 2/29/2010

F02 (750i xDrive Sedan LWB)

Model Year 2010 produced from  
10/15/2008 to 2/22/2010

F07 (550i Gran Turismo and 550i xDrive  
Gran Turismo)

Model Year 2010 produced from  
3/24/2009 to 8/31/2010

All with the N63 engine

#### INFORMATION

For the above-referenced vehicles, BMW of North America, LLC (“BMW NA”) is extending the limited warranty for the **fuel injectors** to:

- **10 years/120,000 miles as determined by the vehicle’s original in-service date**



**This bulletin is notice of a “limited warranty extension.” This is NOT a notice of a Recall or Service Action.**

There is no immediate repair required unless the BMW vehicle is currently experiencing this problem.

#### **Customer Notification Letter – VIN and Component-specific Warranty Extension**

Even though this is **NOT** a Recall, BMW NA will be sending VIN-specific customer notification letters in a phased release during the **first quarter of 2016**.

#### ELIGIBLE BMW VEHICLES

To assist you in identifying the eligible vehicles, the DCSnet Warranty Vehicle Inquiry **will be updated shortly** with the “Vehicle Comment” shown below:

**BMW NA has extended the limited warranty**

**vehicle to 10 years/120,000 miles as determined by component-specific limited warranty extension and coverage eligibility requirements, excluding BMW New Vehicle Limited Warranty for SI B01 01 15.**

---

**Note:** Always check the DCSnet Warranty Vehicle Inquiry “Vehicle Comments” and the “Repair History (Claims)” sections first, before performing any repairs.

#### **PARTS INFORMATION**

Please refer to the Electronic Parts Catalog (ETK/EPC), using the customer’s VIN to locate the applicable replacement part numbers.

#### **Important Notes:**

- **Only order these parts in the quantities needed to address customers’ vehicles that have confirmed failures.**
- **“Only in conjunction with” parts:** When applicable, this ETK/EPC item identifies additional part(s) that must also be replaced/installed together with the replacement of the fuel injectors. These “required” additional items are also covered “in-conjunction” and under the terms of this extended limited warranty.
- Also refer to ETK/EPC and the repair instructions for onetime-use fasteners/screws and other information regarding repair-related gaskets, seals, fluid and/or lubricants that also need to be replaced/used and claimed.

#### **WARRANTY INFORMATION**

The engine fuel injectors limited warranty extension to 10 years/120,000 miles applies to “eligible US-specification BMW vehicles” that are registered, operated and have their covered repair performed by an authorized BMW center in the United

States (including Puerto Rico).

This coverage supersedes the coverage that is provided under the BMW Certified Pre-Owned Program or any BMW Group Vehicle Service Contract that applies to the vehicle.

Should the fuel injectors fail again, they are covered by the remaining portion of the extended limited warranty coverage period.

The existing limited warranty coverage for all other parts **has not** changed.

**Non-Qualifying Repairs**

Non-US specification vehicles, ineligible vehicles, eligible vehicles operated and repaired outside the United States and Puerto Rico and/or the diagnosis and repair of other unrelated issues are not covered under the terms of this limited warranty extension.

**Qualifying Repairs - Claim Submission**

Claim this work with the defect code and the labor operations provided below that apply as needed.

<b>Defect Code:</b>	<b>13 53 90 98 00</b>
---------------------	-----------------------

**Cylinder Bank 1 – 4: Replacing One (1) Fuel Injector**

<b>Labor Operation:</b>	<b>Labor Allowance</b>
00 62 023	Refer to KSD2
Or:	
00 62 575	Refer to KSD2

And, as necessary:

**For Each Additional Fuel Injector on cylinder Bank 1 – 4 Only**

**Cylinder Bank 1 – 4 Only**

<b>Labor Operation:</b>	<b>Labor Allowance</b>
00 62 577	Refer to KSD2
And again for three:	
00 62 577	Refer to KSD2
And again for four:	
00 62 577	Refer to KSD2

Or:

**Cylinders Bank 5 – 8: Replacing One  
(1) Fuel Injector**

<b>Labor Operation:</b>	<b>Labor Allowance</b>
00 62 024	Refer to KSD2
Or:	
00 62 576	Refer to KSD2

And, as necessary:

**For Each Additional Fuel Injector on  
cylinder Bank 5 – 8 Only**

<b>Labor Operation:</b>	<b>Labor Allowance</b>
00 62 578	Refer to KSD2
And again for three:	
00 62 578	Refer to KSD2
And again for four	
00 62 578	Refer to KSD2

Or:

**Both Cylinder Banks - Replacing at least One (1) Fuel Injector on Each Side,**

**Two (2) to Seven (7) or Replacing all Eight (8) Injectors**

Labor Operation:	Labor Allowance
00 62 025	Refer to KSD2
Or:	
00 62 579	Refer to KSD2

And: